Bonndeco Silicone Shield

Modified Acrylic Silicone Resin

Job Reference

B
BONNTILE HONG KONG LTD

Project	Main Contractor /Owner	Year
Wing Shun Building, 64-66 Bonham Strand West, Sheung Wan, Hong Kong	上環文咸西街64-66號永順大廈	2019-2020
On Fung Building, 110-118 Caine Road, Mid-levels West, Hong Kong	香港西半山堅道110-118號安峰大廈	2019-2020
Beverly House, 6 Fung Fai Terrace, Happy, Wan Chai District, Hong Kong Island	香港灣仔跑馬地鳳輝臺6號碧麗苑	2019-2020
Quality Tower, 29-31 Hillwood Road, Tsim Sha Tsui, Kowloon	九龍尖沙咀山林道29-31號廣利樓	2019-2020
No. 28 Hung To Road, Kwun Tong	觀塘鴻圖道28號	2019-2020
黄道益 No. 83 Fuk Yi Street, Yuen Long Industrial Estate	Wongtoyick Company Ltd	2018-2019
海傲灣 One East Coast, 1 Lei Yue Mun Path, Yau Tong	Kowloon Development Company Ltd	2018-2019
No. 66 Robinson Road, Hong Kong	Pilot Building Services Ltd	2017-2018
英皇駿景酒店 Emperor Hotel, 373 Queen's Road East, Wan Chai	Emperor Group	2017-2018
東華三院馬錦燦紀念小學 TWGHs Ma Kam Chan Memorial Primary, 2 Ching Shing Road, Sheung Shui, N.T.	Tung Wah Group of Hospitals	2016-2017
聖士提反書院 St. Stephen's College, 22 Tung Tau Wan Road, Stanley	St. Stephen's College	2016-2017
116 Johnstone Road, Wanchai, Hong Kong		2015-2016

Remarks:-

 We reserve the right to change or adjust the composition of material used in the specification of our products due to our constant research and development to improve of the quality of our products.

Bonntile Hong Kong Ltd : Flat C2., Hang Fung Industrial Building Phase 2, 2G Hok Yuen Street, Hung Hom, Kowloon 邦盛建材香港有限公司: 九龍紅磡鶴園街2G恒豐工業大廈2期11樓C2室 Tel: 2341 9201 Fax: 27635348 E-mail: info@bonntile.com Website:www.bonntile.com.hk

The recommended coverage rates, including those of normal wastage, are for reference only. Actual coverage may vary depending on the working condition of the site, the degree of evenness and smoothness of the substrate surface, and the pattern of the texture sample as selected and approved by the architect or client.